221 - Process Piping Worklist



Report Date: October 08, 2012 Data Source: Meridium

IDENTIFICATION

Worklist ID: <u>WL-1011238174</u>

Equip. Location: 0955-007-001: C-1100 NO. 4 SIDECUT OUTLET **Asset ID:** 0000110906

Unit: 0955: 4 CRUDE UNIT PLT 11 Activity ID: 2011 D&R Major S/D

Date Created: 05/03/2010 **Date Modified:** 11/16/2010

MFR: MFR Model No:

MFR Serial No: Asset Type: 221 - 221 - Process Piping

GENERAL

Bill of Material	
X Staging Required	
Comments:	

WORKLIST ITEMS Signature

_		
	Clean Internally	
	Repair Gasket Surface	
	Hydrotest	
	Hanger	
	Shoes	
	Bolting	
	Dead Leg	
	Supports	
	Insulation	
	Coating	

X	Additional Instruction	hot piping inspection	
X	Additional Instruction	Rope access required	
X	Additional Instruction	damaged or missing cookies will be required following inspection. Estimate required cookies based on the total number of CML locations.	
	Additional Instruction		

Note:

History:

Hot piping inspection can not be performed safely on the run due to special equipment and personel required.

Last Update: October 08, 2012 Content Owner: MERCAB Page 1 of 2

© 2005 Chevron Corporation Technical Owner: Meridium IT Support Company Confidential

CUSA-EPA-0001871

221 - Process Piping Worklist



Report Date: October 08, 2012 Data Source: Meridium **IDENTIFICATION** WL-1005233645 Worklist ID: 0000110906 Equip. Location: Asset ID: 0955-007-001: C-1100 NO. 4 SIDECUT OUTLET 2011 D&R Major S/D Unit: **Activity ID:** 0955: 4 CRUDE UNIT PLT 11 05/26/2010 05/03/2010 Date Modified: Date Created: MFR Model No: MFR: 221 - 221 - Process Piping MFR Serial No: Asset Type: **GENERAL** Available During Run? Bill of Material Staging Required Comments: **Denied WORKLIST ITEMS** Signature Clean Internally Repair Gasket Surface Hydrotest Hanger Shoes **Bolting** Dead Leg Supports Insulation Coating

X	Additional Instruction	Material upgrade to defend against sulfidation corrosion	
	Additional Instruction		
	Additional Instruction		
	Additional Instruction		
	Note:		
	History:		

Last Update: October 08, 2012 Content Owner: MERCAB Page 2 of 2

© 2005 Chevron Corporation Technical Owner: Meridium IT Support Company Confidential